§ 403. Storage of inflammable supplies. No powder or oils shall be stored in any mine, tunnel or quarry, or in or around any shaft, engine or boiler house. All inflammable or destructive supplies shall be stored at safe distances from mine or tunnel openings.